WARNING! Ethidium Bromide

(mutagen, moderately toxic)

Used in this area

While working: Lab coats and nitrile gloves required during use.

When done: Remove and dispose of gloves before leaving area.